


F / G. 1




2/24 F I G. 2







3/24 F I G. 4 A



F / G. 4B




F / G. 5





5/24


F / G. 6 A




F / G. 6 B












F / G. 9




8/24 F I G. 10







F / G. 12



raised regions
depressed regions

F / G. 14






polishing time


polishing time


D1


D2

BL












F / G. 18A



F / G. 18B







the second stage (surface material removal)




F / G. 20A




F / G. 20B




F1G.21




16/24 F I G. 22




F / G. 23A






F1G.24





19/24 F I G. 25




20/24

F I G. 26A










22/24


F / G. 28











F16.30